

# CORRECTION

## Steel Rigid Frames with Leaning Columns

Paper by MICHAEL D. FOLSE and PAUL S. NOWAK  
(4th Quarter, 1995)

Michael D. Folse

Page 127, a note of explanation for Figure 4:

The exterior gravity loads equal the interior values because the exterior wall loads were about the same as floor and roof loads for a half a beam spacing.

Page 130:

For computing  $B_2$ :

$\Sigma P_{e2}$  = sum of in-plane sway buckling capacities of the 2 rigid frame columns =  $(9.87)(29,000)(15,000) / (1.75(192))^2 = 2(38,000) = 76,000$  kips (note that since  $\Sigma P_u$  includes the loads on the leaning columns, it is not necessary to multiply  $k_x$  by  $N^{0.5}$  when calculating  $P_{e2}$ )

$$B_2 \text{ (Eq. 3)} = 1 / (1 - 3590(0.737) / (291.2(192))) = 1.05$$

and

$$B_2 \text{ (Eq. 4)} = 1 / (1 - 3590 / 76,000) = 1.05$$


Page 131:

$$M_{lt} = (1,130 - 1,830) = 9,470 \text{ in-k at top and } (18,900 - 605) = 18,300 \text{ in-k at bottom.}$$

should be changed to:

$$M_{lt} = (11,300 - 1,830) = 9,470 \text{ in-k at top and } (18,900 - 605) = 18,300 \text{ in-k at bottom.}$$

The following are Figures 6a and 6b, which were mistakenly omitted.



*Fig. 6. Plane frame analysis results column moments (in-kips).*