

# ERRATA

## **Torsion Design of Round HSS Members— A Critical Review**

Bo Dowswell

Vol. 61, No. 3, 2024

In Appendix A, Table A-2, the predicted failure modes for Donnell (1935) Specimens 23 and 24 are incorrect. In the fifth and eighth columns, “I” should be changed to “Y” for these two specimens.

