

Errata

Third Quarter, 1973 (Vol. 10, No. 3)

Page 81

The two sentences beginning on the 6th line from the bottom of the left-hand column should read:

“The fundamental frequency of the composite truss system was computed at 4 cycles per second. However, field verification on the actual floor with a portable accelerameter indicated this frequency to be about 5 cycles per sec.”