
CLOSURE

The Effects of Over-Compressing ASTM F959 Direct Tension Indicators on A325 Bolts Used in Shear Connections

Paper by EDWIN R. SCHMECKPEPER, RICHARD J. NIELSEN, and GUY GENTRY
(1st Quarter, 1999)

Closure by Edwin R. Schmeckpeper

The comments concerning Figure 1 on page 40 of the subject paper are correct. There is a drafting error in Figure 1, for Method #2. The location of the DTI and hardened washer are transposed. The correct figure is given below.

It should be noted that the text of the paper which refers to Figure 1, on page 40, paragraph 2, places the DTI in the

correct location. The paper states “in Method No. 2, DTIs are placed under the ‘turned’ part”.

The authors thank Mr. Ricker for bringing this error to our attention.




Fig. 1. (Revised) DTI Installation Methods

Edwin R. Schmeckpeper is associate professor, department of civil engineering, University of Idaho, Moscow, ID.
