

ERRATA

The Behavior of Steel Perimeter Columns in a High-Rise Building under Fire

Paper by MARIA M. GARLOCK and SPENCER E. QUIEL

(4th Quarter, 2007)

Figure 11 should be replaced with the following figure.




Fig. 11. Computational (SAFIR) results for (a) axial load ratio and (b) plastic moment ratio for the column just below Floor 23.

