

ERRATA

Clearance for Welded Joints

Bo Dowswell

Vol. 56, No. 1, 2019

In the paper ABSTRACT, the last two sentences of the paragraph are revised to:

The results of this study, which was limited to only eight specimens, validated the common practice of cutting the edge square at doubler plates less than $\frac{3}{8}$ -in. thick. For doubler plates thicker than $\frac{1}{4}$ in., a groove angle, α , of 15° to 30° may be required to ensure consistent weld quality.

