

Errata

Design of Beam-Columns

Paper presented by IRA HOOPER (April, 1967, Issue)

Page 51

In Step 4 of the recommended procedure for chart solution of Formula (7a), the term $0.75e$ should read $0.75c$.

Page 55

In the 3rd line of the solution, F_b should be 22 ksi instead of 36 ksi.

Page 56

In the abscissa $C_m f_b / F_b$ in the diagram, 0.04 should read 0.4.

Page 60

Under “Given”, the Y dimension of L should read 18 ft instead of 19 ft. The beam size should be 14W211 instead of 14W158.

Page 61

Under “Given”, M_{bot} under Y should read 0, and the term “clockwise” under “Remarks” should be deleted.