
ERRATA

Multiple Bolt Anchorages: Method for Determining the Effective Projected Area of Overlapping Stress Cones

Paper by M. LEE MARSH and EDWIN G. BURDETTE
(1st Quarter, 1985)

On Page 31, Figure 9, correct the equation for the “shaded area” to read as follows:

$$\text{SHADED AREA} = \pi l_e^2 - \frac{2 \cos^{-1} \left(\frac{s}{2l_e} \right) \pi l_e^2}{360 \text{ deg}} + \frac{s}{2} \sqrt{l_e^2 - \frac{s^2}{4}}$$

On page 31, Figure 10, insert missing dimension in far left partial circle, $s/2$.