
ERRATA

Steel Plate Shear Walls are Not Plate Girders

Paper by JEFFREY W. BERMAN and MICHEL BRUNEAU
(Third Quarter, 2004)

Revise Table 2 as follows (revisions are underlined):

Table 2. Sensitivity of C_v

h/t_w	Scenario	C_v^c (Eq. 7)	k_v^c (Eq. 5)	C_v^c (Eq. 7)
144	3658 mm long wall 25.4 mm thick	$k_v/24$	10.0	0.42
576	3658 mm long wall <u>6.4</u> mm thick	$k_v / 379$	10.0	0.026
864	5486 mm long wall <u>6.4</u> mm thick	$k_v / 850$	7.2	0.0084