

ERRATA

Fillet Weld Design for Rectangular HSS Connections

Paper by JEFFREY A. PACKER and MIN SUN
(1st Quarter, 2011)

On p. 32, the line of text prefacing Equation 2b should read:
“When $\theta \geq 60^\circ$.”

On p. 33, the line of text prefacing Equation 4b should read:
“When $\theta \geq 60^\circ$.”

On p. 39, the last sentence in the left column should read:
“The predicted strength of each welded joint, without consideration of the $(1.00 + 0.50 \sin^{1.5} \theta)$ effect...”

The captions of Figures 5 and 6 should be altered to read:
“...without inclusion of the $(1.00 + 0.50 \sin^{1.5} \theta)$ term...”

The headings of Tables 6 and 7 should be altered to end with: “...without Inclusion of the $(1.00 + 0.50 \sin^{1.5} \theta)$ Term”

